GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आजादी का अमृत महोत्सव

No. F.6/DFS/MS/NDZ/2025/ 629 Dated: 22 /12/2025

To,

The Chief Manager,
17, First Floor, Indian Bank Building,
Sansad Marg, New Delhi -110001

Sub: Regarding issuance of Fire Safety Certificate in r/o Allahabad Bank Building, 17, Parliament Street, New Delhi.

Sir,

Please refer your letter No. FGMO/EXP/AK/Fire-Safety/2025-26/(i) dated 22/10/2025, on the subject cited above. In this connection, it is to inform you that the said building was inspected by the officers concerned of this department on 28/11/2025 in the presence of Mr. Ashok Kumar, Chief Manager & Mr. Pankaj Kumar Mishra, Manager Security and observed that shortcomings conveyed vide this office letter No. F.6/DFS/MS/NDZ/2025/342 dated 15/07/2025 (copy enclosed) has not been complied except the shortcoming placed at Sr. No. 4. Further, the following shortcomings were also observed: -

1. Detectors were not provided at some places.
2. Manually Operated Emergency Fire Alarm was not provided at some places in basement.
3. Sprinklers were not provided at some places in the basement.
4. Smoke Management System was not provided in basement.
5. H.T. & L.T. panels were not protected with fire suppression system.
6. Sealing of vertical and horizontal openings was not done at some places.

Further, 4th floor was found locked and 3rd floor was found under renovation.

In view of the above shortcomings, the application for issuance of fire safety certificate cannot be considered at this stage & stand **rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Encl: As Above

19/12/25

(Dr. S. K. Tomar)
Dy. Chief Fire Officer