430

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/NWZ/2025/1902 Dated:- 28/10/2025

To,

Sh. Mukesh Kumar,
Shiv Farm, Palla Bakhtawarpur Road,
Alipur, Delhi-110036.

Sub.:- Regarding issuance of Fire Safety Certificate in r/o M/s. Shiv Farm, Palla, Bakhtawarpur Road, Alipur, Delhi-110036 .

Sir,

This has reference to your letter no. nil dated 19/09/2025 on the subject cited above. In this connection, it is to inform you that the above said building was re-inspected by the officers concerned of this department on dated 13/010/2025 in the presence of Sh. Mukesh (Partner) to check the compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/2017/987 dated 19/04/2017 (copy enclosed).

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above shortcomings, the application for renewal of Fire Safety Certificate cannot be considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

Enclosed: - As above

S.K. Dua
Dy. Chief Fire Officer
West Zone

NCA

cl29

Shiv Farm, Palla Bakhtawarpur Road, Alipur, Delhi-36

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F6/DFS/ms/2017/987 Date: 19/4/2017

To

Shiv Farm,
Palla Bakhtawarpur Road,
Alipur, Delhi-36

Sub: -Regarding Fire safety Certificate in M/s Shiv Farm, Palla Bakhtawarpur Road, Alipur, Delhi-36

Sir,

Please refer to your letter No- nil dated 14/03/2017 on the subject noted above. In this connection, this is to inform you that the inspection of the above said premises was carried out by the officers concerned of this department along with Sh. Suresh Kumar Owner) on 30/03/2017 to verify the fire safety arrangements. However the following shortcomings were observed.

1. Fire extinguishers of ABC/Co2 type not provided against the 05 no's of ABC / Co2 type 2.5 kg capacity required to be provided
2. Hose reel provided but not functional & found removed on ground floor.
3. Manually operated electric fire alarm not functional.
4. Yard hydrants found removed on ground floor.

You are requested to comply the shortcoming under intimation to this department

Yours faithfully

(Atul Garg)
Chief Fire Officer
Ph: 011-23414250

9cl