GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/SCHOOL/SZ/2026/ 614 Dated: 03/07/2026

To,

The Principal,
Harsh Public School
E – 19, Jai Vihar, Najafgarh,
New Delhi – 110043.

Subject: - Regarding Grant of Fire Safety Certificate in r/o M/s Harsh Public School located at E – 19, Jai Vihar, Najafgarh, New Delhi – 110043.

Sir,

Please refer to your email dated 04/05/2026 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on 12/06/2026 in the presence of Mrs. Banita & Mr. Rajesh Kumar (Manager) and observed that the shortcoming are still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2019/SZ/6309 dated 22/10/2019 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

01/07/26

(S. K Dua)
Chief Fire Officer
Delhi Fire Service

Enclosed: As above

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi – 110054.

C 3

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2019/SZ / 6309 Dated: 22/10/19

To,

The Principal,
Harsh Public School,
E-19, Jai Vihar, Najafgarh, New Delhi-110043

Sub: - Regarding issuance of Fire Safety Certificate in r/o Harsh Public School, E-19, Jai Vihar, Najafgarh, New Delhi-110043.

Sir,

This has reference to your Letter No. Nil dated Nil on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 26.09.2019 to see the requisite fire safety measures. Sh. Rajesh Kumar Chouhan (Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground plus one upper floor and one room on terrace. The upper floors are served by two staircases having width 120 cms & 100 cms. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

1. The building is not approachable through 06 meter wide road.
2. The upper floors are served by two staircases having width 120 cms & 100 cms against required two staircases having width 150 cms each from Ground floor to terrace.
3. Door width is 90 cms against required 120 cms.
4. Hose reel system is not provided.
5. Fire pump having capacity 450 LPM not provided for hose reel system.
6. Overhead water storage tank of 10,000 ltrs capacity not provided for hose reel system.
7. Exit signs are not provided.

- If student capacity is more than 45 in any class room then double door having width 120 cms is required.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
CHIEF FIRE OFFICER

Copy to:-

Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi – 110054
(with a request to take further action as school does not have fire NOC)

Scanned with OKEN Scanner