GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52025121700688 **Dated: 20-04-2026**

SHORTCOMING(S)

With reference to your application ID **52025121700688** dated **20-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Arun Hosiery Mill** at **Shes no. -151 Okhla Industrial Estate, Ph-III, New Delhi-110020** from fire safety point of view in presence of **Mr. Arun Gulati** on dated **18/03/2026** During the course of inspection following observations were made:-

1- Fire check Door found removed.
2- Smoke Management System found removed.
3- Automatic Sprinkler System provided but not functional.
4- Fire pump of capacity 900 LPM provided but not functional.
5- Overhead water tank of capacity 20,000 liters is provided against requirement of 25,000 liters.
6- Exit & floors Signage's not provided at strategic location in the building.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-
1. ARUN GULATI , 15-BLK, EAST AEVNUE, MAHARANI BAGH, DELHI, 110065
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.