GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026010500089 **Dated: 21-04-2026**

SHORTCOMING(S)

With reference to your application ID **52026010500089** dated **21-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Lord Krishna Convent School** at **Gali No. 94, Opposite Apex Main Gate, Sant Nagar, Burari, Delhi-110084** from fire safety point of view in presence of **Sh. Subhash Chandra Bose, Owner** on dated **10/04/2026** During the course of inspection following observations were made:-

1. The second staircase, meant for emergency egress, was found obstructed due to placement of desks, thereby compromising the means of escape.
2. The required overhead fire pump of 450 LPM capacity has not been installed; instead, a pump of lesser capacity is provided.
3. The overhead water storage tank of 2000 liters capacity is inadequate against the required capacity of 10,000 liters.
4. Exit signages have not been provided at the strategic locations.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Chief Fire Officer

Copy to:-
1. SUPRIYA GUPTA , KHSRANO 125/20 , Gali no 94 B-Block, sant nagar burari , delhi, 110084
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.