GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026011300257 **Dated: 28-01-2026**

SHORTCOMING(S)

With reference to your application ID **52026011300257** dated **28-01-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Rajshani flour Mills Ltd.** at **C-45/4, Lawrence Road Industrial Area, New Delhi-110035** from fire safety point of view in presence of **Mr. Mohmmad Ali Fire Safey Manager** on dated **20/01/2026** During the course of inspection following observations were made:-

1.Fire Check Doors (FCDs) were found removed at some places.
2.Building alternate exit of found removed/blocked in basement.
3.Building found not matching with the approved building plans

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Dy.Chief Fire Officer

Copy to:-
1. Satender Kumar Jain , C-45/4, Lowrence Road , Industrial Area, New Delhi, 110035
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.