GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026011700363 **Dated: 28-01-2026**

SHORTCOMING(S)

With reference to your application ID **52026011700363** dated **28-01-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Govt. Sarvodaya Kanya Vidhyalaya** at **Badli, Delhi-110042.** from fire safety point of view in presence of **Sh. Parmod (Gaurd)** on dated **21/01/2026** During the course of inspection following observations were made:-

1. Electrical panel below at 'A' block ground floor needs to be removed/ shifted in a safer place or covered by fire check door.
2. Hose reel hose is provided but not functional some hose reel nozzles found missing.
3. Internal hydrant is provided but not functional and damaged condition.
4. Terrace level fire fighting pump capacity of 450 Lpm is provided but not functional and badly leakage/ damaged condition.
5. One inspection ladder also required for overhead water storage tank for inspection purpose in (G+2) A block & (G+3) E block.
6. Standby power supply is not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Dy.Chief Fire Officer

Copy to:-
1. Jagmohan , GBSSS BADLI, NEAR NCC BHAWAN, VILLAGE BADLI, ROHINI, 110042
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.