GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026012300523 **Dated: 10-03-2026**

SHORTCOMING(S)

With reference to your application ID **52026012300523** dated **10-03-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **The Kunj Vihar CGHS Ltd.** at **Plot No. 19, Sec. 12, Dwarka, New Delhi- 110075** from fire safety point of view in presence of **Mr. Shyam, Caretaker** on dated **24/02/2026** During the course of inspection following observations were made:-

1. Hose reels/hydrant found removed in basement and not functional in upper floors level.
2. Automatic sprinkler system provided in basement but found not functional.
3. Yard hydrant provided but not functional.
4. Terrace level Fire pumps provided found not functional.
5. Exit Signs found removed at some places.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Dy.Chief Fire Officer

Copy to:-
1. SUDARSHAN KUMAR SARIN , a 104, plot no 19, kunj vihar , delhi , 110075
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.