GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026012800612 **Dated: 12-02-2026**

SHORTCOMING(S)

With reference to your application ID **52026012800612** dated **12-02-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Ram Swaroop Sethi Saraswati Shishu Mandir** at **2754/A, Ranjit Nagar, New Delhi- 110008.** from fire safety point of view in presence of **Ms. Geeta Tuli, Principal** on dated **09/02/2026** During the course of inspection following observations were made:-

1. First Aid Hose reel at each floor level found not provided.
2. Terrace pump capacity of 450 LPM found not provided.
3. Overhead Water storage tank capacity of 10,000 ltrs found not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Dy.Chief Fire Officer

Copy to:-
1. DEEPAK SETH , 515-516 2nd floor , double storey , rajender nagar , central delhi, 110060
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.