GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026021701083 **Dated: 15-05-2026**

SHORTCOMING(S)

With reference to your application ID **52026021701083** dated **15-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **CSIR Scientist Apartment** at **MBSA, Ashram Chowk, New Delhi-110014** from fire safety point of view in presence of **Abhay Kumar Jha - AE** on dated **17/04/2026** During the course of inspection following observations were made:-

1.First-Aid-Hose Reel provided but found nonfunctional.
2. Internal and Yard Hydrants provided but found non functional.
3.Pumping arrangements provided but found nonfunctional.
4.Exit & floors Signage's not provided at strategic location in the building.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-
1. Abhay Kumar Jha , H.No.-C-1/274, Street No.-23, Khajoori Khas Colony, Delhi, 110094
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.