**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

**Application ID. 52026021701086** **Dated: 07-04-2026**

# SHORTCOMING(S)

With reference to your application ID **52026021701086** dated **07-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **DR. B.R. AMBEDKAR, C.B. SR. SEC SCHOOL** at **MEHRAM NAGAR, DELHI CANTT, NEW DELHI - 110010** from fire safety point of view in presence of **Smt. Bala Singhal, Principal** on dated **25/02/2026** During the course of inspection following observations were made:-

1. Fire Extinguisher found non functional.
2. Hose reel Hose found non functional.
3. Discharge and head of pump found non functional.
4. Overhead tank found empty.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

**A.K.Malik**
**Dy.Chief Fire Officer**

**Copy to:-**

1. Chief Executive Officer , Delhi Cantonment Board, Sushma Swaraj Marg, Sadar Bazar, Delhi Cantt, Delhi, 110010
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.