**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

**Application ID. 52026031601659** **Dated: 16-05-2026**

# SHORTCOMING(S)

With reference to your application ID **52026031601659** dated **16-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Vallabhbhai Patel Chest Institute** at **University of Delhi, Delhi-110007** from fire safety point of view in presence of **Sh. Sunil Kumar Yadav** on dated **29/04/2026** During the course of inspection following observations were made:-

1.Ventilation arrangements in the building corridors were found removed.
2.Fire extinguishers were found removed from several designated location.
3.Fire pump is not on auto operation.
4.Fire hydrant cabinets were found damaged at multiples locations.
5.MOEFA found non-functional.
Smoke detectors were found removed from their bases at several locations.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

**S.K.DUA**
**Chief Fire Officer**

**Copy to:-**
1. SUNIL KUMAR YADAV , WZ-77-A, GALI NO-1, , MAHAVIR ENCLAVE, VALMIKI , VIHAR, NASIRPUR ROAD , PALAM, 110045
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.