**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

**Application ID. 52026032701879** **Dated: 21-04-2026**

# SHORTCOMING(S)

With reference to your application ID **52026032701879** dated **21-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Dr. B.R. Ambedkar CM Shri School** at **Sector-21, Phase-II, Delhi-110085.** from fire safety point of view in presence of **Sh. Devender Dutt (PGT)** on dated **09/04/2026** During the course of inspection following observations were made:-

1. Terrace floor door found opening inwards in contravention NBC/UBBL.
2. Terrace pumps are not operational as panel has no electrical supply.
3. Exit door provided with locking door in corridors & stair.
4. Auditorium doors 04 nos. of 1.50 m each found provided against the requirement of 2.0 mtr door.
5. Electrical panel found provided below staircase needs to be shifted in a safer place.
6. Hose reel is provided but not functional.
7. Fire protection system found non-functional.
8. Another hall was found constructed on terrace with double height making building Ground+04 upper floors.

Therefore you are advised to submitted building plans of the school for further consideration in this matter.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

**S.K.DUA**
**Chief Fire Officer**

**Copy to:-**
1. NARENDRA SINGH , I- 7/ 67, SEC- 16 ROHINI, SECTOR - 16 ROHINI , DELHI, 110089
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.