GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026042702534 **Dated: 26-05-2026**

SHORTCOMING(S)

With reference to your application ID **52026042702534** dated **26-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Sapru House - ICWA** at **Barakhamba Road, New Delhi** from fire safety point of view in presence of **Sh. Dheeraj Mishra, AE Electrical PWD and Sh. Kamal Singh, Assistance Maintenance** on dated **19/05/2026** During the course of inspection following observations were made:-

1. Smoke Management System found removed in basement.
2. Smoke/Heat detectors provided but found non-functional.
3. Manually Operated Electronic Fire Alarm (MOEFA) provided but found non-functional.
4. Public address system provided but found non-functional.
5. Automatic sprinkler system found removed at some places.
6. Total 02 nos. Hose reels provided against the required quantity of 05 nos.
7. Automatic Operation of Fire pumps near underground water storage tank found removed.
8. Terrace pump provided but found non-functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Dr.S.K.Tomar
Chief Fire Officer

Copy to:-
1. Kamal Singh , ICWA, Sapru House, Barakhamba Road, Barakhamba Road, New Delhi, 110001
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.