**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

**Application ID. 52026042702558** **Dated: 29-05-2026**

# SHORTCOMING(S)

With reference to your application ID **52026042702558** dated **29-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Government of India Press** at **Minto Road, Pocket-II, DDU Marg, Connaugh Place, New Delhi - 110001** from fire safety point of view in presence of **Sh. Balraj Singh, Assistant Inspector Control and Sh. Mayank, AE-Electrical CPWD** on dated **19/05/2026** During the course of inspection following observations were made:-

1. Pressurization System installed in Staircases, Lift Shafts and Lift Lobbies but found non-functional.
2. Smoke Management System provided but found non-functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

**Dr.S.K.Tomar**
**Chief Fire Officer**

**Copy to:-**
1. MAYANK RAUTHAN , EE E DED11, B 506 IP Bhawan, ITO, Delhi, 110002
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.