GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026060403366 **Dated: 09-09-2026**

SHORTCOMING(S)

With reference to your application ID **52026060403366** dated **09-09-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Govt. Boys. Sr. Sec. School (School Id-1412086)** at **E-Block, Sultanpuri, Delhi-110086.** from fire safety point of view in presence of **Mr. Sachin Kumar (Teacher)** on dated **13/08/2026** During the course of inspection following observations were made:-

1. Fire extinguisher is provided but not functional.
2. Hose reel hose is provided but not functional & nozzle is found missing.
3. Terrace level fire pump of 450 LPM capacity is provided but not functional.
4. Down comer system (riser) is found leakage condition.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-
1. BRIJESH KUMAR SINGH , GBSSS, E-BLOCK, SULTANPURI, DELHI, 110085
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.