GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026061903802 **Dated: 27-07-2026**

SHORTCOMING(S)

With reference to your application ID **52026061903802** dated **27-07-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Maharishi Dayanand Model Sec. School** at **134, Arvind Enclave, Nangloi, New Delhi-110041.** from fire safety point of view in presence of **Mrs. Nisha, Vice Principal** on dated **14/07/2026** During the course of inspection following observations were made:-

1.First Aid hose reel found removed from the ground floor.
2.Terrace fire pumps were not found in auto mode during inspection.
3.4000 ltrs Over Head water captive tank provided against the required capacity of 5000 ltrs.
4.Exit signage's found removed at some places.
5.One room was found constructed on the second-floor terrace

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-
1. Nisha Antil , 134 Arvind Enclave , Amar Colony, Nangloi, Delhi, 110041
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.