GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026062203884 **Dated: 22-10-2026**

SHORTCOMING(S)

With reference to your application ID **52026062203884** dated **22-10-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Indian Social Institue** at **Plot No. 10, 11 and 12, Lodhi Institutional Area, Lodhi Road, New Delhi-03.** from fire safety point of view in presence of **Sh. Pawan Kumar, Admin Officer** on dated **08/09/2026** During the course of inspection following observations were made:-

1.Exhaust fans in the basement are blocked by fix panels.
2.Hose reel found not provided in Basement.
3.Fire Check Doors Found removed.
4.Automatic Fire Detection and Alarm System found non functional.
5.All water based Systems like Fire Pumps, Hose Reels, Internal Hydrants, Sprinklers are non- functional.
6.Mannuel Operated Electrical Fire Alarm System (MOEFA) Found non functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-
1. CYRIL A , 6/22A, MURUGESAN STREET, PERAMBUR, CHENNAI, 600011
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.