**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

**Application ID. 52026062403946** **Dated: 06-10-2026**

# SHORTCOMING(S)

With reference to your application ID **52026062403946** dated **06-10-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Indian Social Institute** at **Plot no. 21, Institutional Area, Lodhi Road, New Delhi-03.** from fire safety point of view in presence of **Sh. Pawan Kumar, Admin Officer** on dated **08/09/2026** During the course of inspection following observations were made:-

1.Exhaust fans in the basement are blocked by fix panels.
2.Fire Check Doors Found removed.
3.Electrical shaft not found not sealed.
4.All water based Systems like Fire Pump, Hose Reels, Internal Hydrants are non- functional
5.Mannuel Operated Electrical Fire Alarm System (MOEFA) Found non functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

**A.K.Malik**
**Chief Fire Officer**

**Copy to:-**
1. CYRIL A , 6/22A, MURUGESAN STREET, PERAMBUR, CHENNAI, 600011
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.