GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026062904040 **Dated: 23-10-2026**

SHORTCOMING(S)

With reference to your application ID **52026062904040** dated **23-10-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Deepali Building** at **92, Nehru Place, New Delhi-110019** from fire safety point of view in presence of **Sh Rajesh kumar** on dated **16/09/2026** During the course of inspection following observations were made:-

1. Fire Check door found removed at some places.
2. Type of detectors found removed in some offices and floors.
3. Public Address system provided but not functional.
4. Pressurization of lift shaft and lift lobby is not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-
1. RAJESH KUMAR SONI , HOUSE NO 66, BLOCK D, GULMOHAR PARK, NEW DELHI, 110049
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.