GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026062904050 **Dated: 20-11-2026**

SHORTCOMING(S)

With reference to your application ID **52026062904050** dated **20-11-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **JAN KALYAN SAMITEE** at **PLOT NO 15 R.K PURAM, NEW DELHI- 110022** from fire safety point of view in presence of **Pawan Kumar** on dated **15/09/2026** During the course of inspection following observations were made:-

1. Width of staircases 1 x 1.5m, 1x 1.10m are provided against requirement of 1.5m respectively.
2. Fire Check Doors Found removed.
3. Smoke management system provided in basement but found not functional.
4. First Aid Hose Reels provided but found not functional.
5. MOEFA provided but found not functional.
6. Automatic Sprinkler system in basement provided but found not functional.
7. Internal Hydrants system provided but found not functional.
8. Ground level pump discharge of 1620 LPM, Jockey pump out put 180 LPM, Standby pump out put 1620LPM, terrace level pump discharge of 450 LPM are provided but found not functional and Auto start of pump found not functional.
9. overhead tank capacity of 20,000 ltrs is provided but found empty.
10. Pressurization of lift shaft and lift lobby not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-

1. PAWAN KUMAR MENDIRATTA , H NO 202, SECTOR 4 B, VASUNDHARA, GHAZIABAD, 201012
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.