GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026063004094 **Dated: 05-08-2026**

SHORTCOMING(S)

With reference to your application ID **52026063004094** dated **05-08-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **St. Mathew s School** at **A-6, Paschim Vihar, New Delhi-110069.** from fire safety point of view in presence of **Mrs. Anita** on dated **23/07/2026** During the course of inspection following observations were made:-

1.One (01) First Aid Hose Reel was found removed from the ground floor, and another First Aid Hose Reel was found installed beneath the staircase.

2.Terrace fire pumps having capacities of 450 LPM and 180 LPM was found removed at the time of inspection.

3.Exit signages were found removed at some locations.

4.One side of the exit corridor on the 3rd floor was found blocked with a brick wall.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-

1. ANITA SETHI , ST MATTHEWS PUBLIC SCHOO, A 6 PACHIM VIHAR, PASCHIM VIHAR, NEW DELHI, 110063
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.