GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026071704521 **Dated: 17-11-2026**

SHORTCOMING(S)

With reference to your application ID **52026071704521** dated **17-11-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Guru Ram Dass CGHS Ltd.** at **Plot No. 3, Sector- 22, Dwarka, New Delhi- 110075** from fire safety point of view in presence of **Sh. Sudhakar Bharti** on dated **15/10/2026** During the course of inspection following observations were made:-

1. The internal road all around the building found encroached/ blocked. The internal road must be free form any obstruction.
2. First Aid hose reels provided but found not functional.
3. Sprinkler system provided but found not functional in basement.
4. Internal hydrant and Yard hydrant provided but found not functional.
5. Terrace level pumps provided but found not functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-
1. Sudhakar Bharti , F 448A/4 , GALI NO 23, SADHANAGR PAALAM COLONY, DELHI, 110045
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.