GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026072804731 **Dated: 22-10-2026**

SHORTCOMING(S)

With reference to your application ID **52026072804731** dated **22-10-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **MCD Multi Level Underground Car Parking** at **Munirka Market, Palam Marg, New Delhi-110067.** from fire safety point of view in presence of **Sh Prashant Balia** on dated **15/09/2026** During the course of inspection following observations were made:-

1. Fire Check Door Found removed at some places.
2. Smoke Management system in basement Provided but not functional.
3. First Aid Hose Reels Provided but not functional.
4. Type of detectors Provided but not functional.
5. MOEFA Provided but not functional.
6. Public Address system Provided but not functional.
7. Automatic Sprinkler system in basement Provided but not functional.
8. Internal hydrants Provided but not functional.
9. Discharge of main pump 1800 LPM, Jockey pump out put 2 x 180 LPM, Standby pump out put 1800 LPM Provided but not functional.
10. Access to tank Not Provided.
11. Exit Signage found removed.
12. Pressurization of lift shaft and lobby Provided but not functional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Sachin Rana, IAS
Pr. Director

Copy to:-
1. PRASHANT BALIA , E-85 TYPE IV, MCD OFFICERS COLONY, MINTO ROAD, New Delhi, 110002
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.