C-33

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/WZ/School/2026/ 602 Dated: - 02/07/2026

To,

The Principal,
Dr. B. R. Ambedkar CM Shri School,
Sector-21, Phase-II, Delhi-110085.

Sub.: - Regarding renewal of Fire safety Certificate in r/o Dr. B.R. Ambedkar CM Shri School, located at Sector-21, Phase-II, Delhi-110085.

Sir,

This has reference to DFS online portal application no. 52026052203105 on the subject cited above, it is to inform you that the said building premises was re-inspected by the officer concerned of this department on 13/06/2026 in the presence of Sh. Arjun Singh (Estate Manager) to check the compliance of shortcomings issued by this department vide application ID No. 52026032701879 dated 21/04/2026 (copy enclosed).

During inspection, it has been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above, the application for renewal of Fire Safety Certificate cannot be considered at this stage & **rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

01/07/26

(S.K. Dua)
Chief Fire Officer
Delhi Fire Service

Copy to :-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054.

C-33

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/WZ/School/2026/ 602 Dated: - 02/07/2026

To,

The Principal,
Dr. B. R. Ambedkar CM Shri School,
Sector-21, Phase-II, Delhi-110085.

Sub.: - Regarding renewal of Fire safety Certificate in r/o Dr. B.R. Ambedkar CM Shri School, located at Sector-21, Phase-II, Delhi-110085.

Sir,

This has reference to DFS online portal application no. 52026052203105 on the subject cited above, it is to inform you that the said building premises was re-inspected by the officer concerned of this department on 13/06/2026 in the presence of Sh. Arjun Singh (Estate Manager) to check the compliance of shortcomings issued by this department vide application ID No. 52026032701879 dated 21/04/2026 (copy enclosed).

During inspection, it has been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above, the application for renewal of Fire Safety Certificate cannot be considered at this stage & **rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

01/07/26

(S.K. Dua)
Chief Fire Officer
Delhi Fire Service

Copy to :-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054.

409

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026032701879

Dated: 21-04-2026

SHORTCOMING(S)

With reference to your application ID **52026032701879** dated **21-04-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Dr. B.R. Ambedkar CM Shri School** at **Sector-21, Phase-II, Delhi-110085.** from fire safety point of view in presence of **Sh. Devender Dutt (PGT)** on dated **09/04/2026** During the course of inspection following observations were made:-

1. Terrace floor door found opening inwards in contravention NBC/UBBL.
2. Terrace pumps are not operational as panel has no electrical supply.
3. Exit door provided with locking door in corridors & stair.
4. Auditorium doors 04 nos. of 1.50 m each found provided against the requirement of 2.0 mtr door.
5. Electrical panel found provided below staircase needs to be shifted in a safer place.
6. Hose reel is provided but not functional.
7. Fire protection system found non-functional.
8. Another hall was found constructed on terrace with double height making building Ground+04 upper floors.

Therefore you are advised to submitted building plans of the school for further consideration in this matter.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Chief Fire Officer

Copy to:-

1. NARENDRA SINGH , I- 7/ 67, SEC- 16 ROHINI, SECTOR - 16 ROHINI , DELHI, 110089
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.