GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001 C-63

No. F.6/DFS/MS/SZ/school/2025/ 880 Dated: 11./.12/2025

To

The Principal,
Amity International School,
M Block, Saket, New Delhi.

Sub: Regarding issuance of FSC in r/o **M/s** Amity International School, M Block, Saket, New Delhi.

Sir,

This has reference to your letter no. nil dated 17.10.2025, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 13/07/2023 in the presence of Principal and the following shortcomings were observed:-

1. Width of entrance gate is provided of 4.5 m against the requirements of 06 meter .
2. Fire Check Doors are not provided at staircases.
3. Basement is being used for class room instead of service room /storage as approved in the building plan.
4. Alternate staircase /exit serving to basement found blocked.
5. Pressurization is not provided in lift/lift lobby.
6. Pump not in auto mode provision and diesel pump found nonfunctional.
7. Smoke Management system found nonfunctional.
8. MOEFA founds nonfunctional.
9. Only one staircase serving to terrace level against the required of three staircases.

In view of above, Fire Safety Certificate (FSC) cannot be considered at this stage. Further, the occupancy of the building/premises in absence of requisite fire safety arrangements shall be at risk and liability of owner/occupier. Therefore, it is requested to rectify the above shortcomings at the earliest for further consideration in the matter inform to this department.

Yours faithfully,

(A.K.Malik)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to :

1. Director of Education , old Secretariat , New Delhi