GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/2026/SZ/405 Dated: 05/03/2026

To,

The Arya Auditorium ,
Des raj Campus, C Block,
East of kailash, New Delhi,
New Delhi-110065.

Subject: - Regarding issuance of Fire Say Certificate in r/o M/s Arya Auditorium , Des raj Campus, C Block, East of kailash, New Delhi-110065.

Sir,

This has refer to your letter no. nil dated nil received through Gmail dated 02/02/2026 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 17/02/2026 in presence of Mr. Rahul and observed that the shortcomings issued by this department vide letter no. F6/DFS/MS/Auditorium/2025/SZ/371 dated 11/08/2025 (copy over leaf) has not been complied yet.

In view of above Shortcomings, the application for issuance of Fire Safety Certificate is rejected. Further, the occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Encl: As above

(A.K. Malik)
Dy. Chief Fire Officer
Delhi Fire Service

आज़ादी का अमृत महोत्सव

No. F6/DF

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/Auditorium/ 2025/SZ/371 Dated 11/08/2025

To

Arya Orphanage, Arya Auditorium
(Formerly Lalit Suri Auditorium)
Des Raj Campus, C-Block,
East of Kailash, New Delhi – 110065

Sub: - Regarding issuance of fire safety certificate in r/o Arya Orphanage, Arya Auditorium (Formerly Lalit Suri Auditorium) Des Raj Campus, C-Block, East of Kailash, New Delhi - 110065

Sir,

This has reference to your letter no nil dated 14-07-2025, received through outdoor diary 15/07/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 24.07.2025 in the presence of Mr. Neeraj Kumar to verify the fire safety measures installed in the building. During inspection, following points were observed:

1 First Aid Hose reel hose found non- functional.
2 Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.
3 Automatic sprinkler system found non- functional in the basement and upper floor.
4 Internal hydrants and yard hydrant found non- functional.
5 Electrically pump capacity of 2800 LPM, & one jockey pumps of 180 LPM with 60 m head found non- functional
6 Terrace level pump capacity 450 LPM found non- functional.
7 Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully

5/8/2025

(VIRENDRA SINGH)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE