C-7

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2026/WZ/ 248 Dated: 25/03/2026

To,

The Principal,
Bal Bharti Modern School,
Main Rohtak Road,
Tikri Kalan, Delhi-110041.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Bal Bharti Modern School located at Main Rohtak Road, Tikri Kalan, Delhi- 110041.

Sir,

This has reference to your email id dated 06.03.2026 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 12.03.2026 in presence of Smt. Renu to see the compliance of requisite fire safety measures.

Your request for issuance of FSC is rejected due to the following shortcomings:-

1. Width of staircase found 0.85 m and 0.80 m against the required width of 1.5 m each.
2. There is only one staircase reaches up to the terrace against the requirement of both the staircase reach up to the terrace.
3. First aid hose reel found not provided.
4. Terrace level pump of 450 lpm discharge capacity found not provided.
5. Overhead tank of 10,000 ltrs capacity found not provided.
6. Exit signage's not provided.
7. Building plan in a scale of 1:100 duly signed by Regt. Architect and owner is not provided.

You are advised to rectify the above-mentioned shortcomings under intimation to this department.

Yours Faithfully

24/03/26

(S.K. Dua)
Dy. Chief Fire Officer (WZ)
Delhi Fire Service

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, Delhi.