GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/Assembly/SZ/2025/ 628 Dated: 19/12/2025

To,

The Executive Engineer (E)/DDA),
DDA Community Hall Pocket – 5,
Jasola, New Delhi – 110025.

Subject: - Regarding grant of Fire Safety Certificate in r/o DDA Community Hall located at Pocket – 5, Jasola, New Delhi – 110025.

Sir,

This has a reference to your Outdoor Dairy No. 7667 dated 30.10.2025 on the subject cited above. In this connection, it is to inform you that school was inspected by the officer concerned of this department on 08/12/2025 in the presence of Md. Liyakat Hussain (Executive Engineer (E)/DDA) and observed that school building comprised of Ground, Stilt plus three upper floors.

Following shortcomings were observed during time of inspection:

1. First-Aid Hose reel provided but not functional.
2. Internal Hydrants provided but not functional.
3. Pumping arrangements provided but not functional.
4. Water tank for Fire Fighting provided but found empty.
5. Exit & floors Signage's not provided at strategic location in the building.
6. Lifts Signage found removed.

In view of above shortcomings, the application for **issuance of Fire Safety Certificate is rejected**. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

You're faithfully,

19/12/25

(A.K. Malik)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to: -

1. The Chief Engineer South, DDA, Vikas Sadan, New Delhi – 110023.
2. The Executive Engineer (E), DDA, Electrical Division No. 1, Seed Bed Park, School Block Shakarpur, Delhi - 110092.