C-85

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/EH/WZ/2026/ 684 Dated: - 11/08/2026

FIRE SAFETY CERTIFICATE

Certified that the Dilli Darbar, located at Unit No. 114 to 121, 112, 113 and 124, 1st Floor, Plot No. 15, N.N. Mall, Mangalam Place, Sector-3, Rohini, Delhi-110085, restaurant is running at 1st Floor only in the building comprised of 02 basement, ground + 05 upper floors, owned/occupied by Dilli Darbar, was issued Fire Safety Certificate by this department Vide Letter No. F6/DFS/MS/2023/WZ/EH/42 dated 01/02/2023. The restaurant premise was re-inspected by the officer concerned of this department on 20/07/2026 in the presence of Sh. Vijay and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly Building" Group D (Restaurant is running at 1st floor only) with effect from 11/08/2026 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on ..11/08/2026.. at New Delhi by.

10/8/26
(A.K. Malik)
Chief Fire Service
Delhi Fire Service

Copy to: -

1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002 :- in r/o online application id. 2026070609583 dated 06/07/2026.
2. The Authorized Signatory, Dilli Darbar, located at Unit No. 114 to 121, 112, 113 and 124, 1st Floor, Plot No. 15, N.N. Mall, Sector-3, Rohini, Delhi-110085.

Conditions for the validity of fire safety certificate: -

1. This Fire Safety Certificate is valid only for restaurant on 1st floor for assembly occupancy only in case of any violation, this FSC will be treated as null & void.
2. All the means of escape shall be kept free of all type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the firefighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
7. All comments / directions of licensing Department shall always be permitted and followed.
8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building	M/s Dilli Darbar, located at Unit 114 to 121, 112, 113 & 124, 1st floor, Plot No. 15, N.N. Mall, Mangalam Place, Sector-3, Rohini, New Delhi-110085.
2. Composition of building	02 Basement + Ground + 05 Upper Floors but **restaurant is running at 1st floor only.**
3. Type of Occupancy	Assembly (Restaurant)
4. Type of Case	Renewal
5. Details of Previous NOC	F6/DFS/MS/2023/WZ/EH/42 dated 01/02/2023
6. Fire Safety directives letter No	Nil
7. Date of inspection	20/07/2026
8. N/Ame of Inspecting Officer	Paras Kumar, ADO (Rohini)
9. Name and designation of officers From the building side	Sh. Vijay
10. Year of Construction	2004
11. Applicant's online application no.	2026070609583 dated 06/07/2026

S. No	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC-2016 Requirements	Provided at site	Remarks MR/NMR
1.	**Access to building (NN Mall FSC issued vide letter no. – F6/DFS/MS/2025/WZ/577 dated 29/10/2025)**			
	• Road width	06 m	09 m	MR
	• Gate width	N/A	Directly Accessible	N/A
	• Width of interN/Al road	N/A	N/A	N/A
2.	**Number, Width, Type & Arrangement of Exits (Provided & Maintained by Mall Management)**			
	a. Number of staircases			
	• Upper Floors	02 nos.	Provided	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper Floor	1.50 m	Provided	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	Required	Provided	MR
	e. Width of Corridor	N/A	N/A	N/A
	f. Door Size	1.50 m x 2	Provided	MR
3.	**Compartmentation**			
	a) Fire check door	Required	Provided	MR
	b) Sealing of electrical shafts	N/A	Provided	N/A
	c) Fire Rating of shaft door	N/A	Provided	N/A
	d) Water Curtain	N/A	N/A	N/A
	e) Fire Dampers	N/A	N/A	N/A
4.	**Smoke Management System (Provided & Maintained by Mall Management)**			
	a) Basements	N/A	N/A	N/A
	b) Upper floors	12 ACPH	Provided	MR
5.	**Fire Extinguishers**			
	a) Total numbers	04 nos.	Provided	MR
	b) Types	ABC/Co2	Provided	MR
	c) IS marking	Yes	Provided	MR
6.	**First-Aid Hose Reels (Provided & Maintained by Mall Management)**			
	a) Total numbers on each floor	01	Provided	MR
	b) Length of hose reel hose	30m	Provided	MR
	c) Nozzle diameter	5mm	Provided	MR

7.	**Automatic fire detection and alarming system**			
	a) Type of detectors	N/A	Smoke/Heat	N/A
	b) Location of Main Panel	N/A	Ground Floor	N/A
	c) Location of Repeater Panel	N/A	N/A	N/A
	d) Alternate source of power	N/A	Provided	N/A
	e) Hooters' Location	N/A	Provided	N/A
8.	**MOEFA**	Required	Provided	MR
9.	**Public Address System**	N/A	Provided	N/A
10.	**Automatic Sprinkler System**	**(Provided & Maintained by Mall Management)**		
	a) Basement	N/A	Provided	N/A
	b) Ground Floor/Upper Floor	N/A	Provided	N/A
	c) Sprinkler above false ceiling	N/A	Provided	N/A
11.	**Internal Hydrants**	**(Provided & Maintained by Mall Management)**		
	a) Size of riser/down-comer	Required	Provided	MR
	b) Number of hydrants per floor	Required	Provided	MR
	c) Hose Box	Required	Provided	MR
12.	**Yard Hydrants**	**(Provided & Maintained by Mall Management)**		
	a) Total number of hydrants	N/A	Provided	N/A
	b) Hose Box	N/A	Provided	N/A
13.	**Pumping Arrangements**	**(Provided & Maintained by Mall Management)**		
	• Ground Level			
	➢ Discharge of main Pump	N/A	2280 LPM	N/A
	➢ Head of Main pump	N/A	60 m	N/A
	➢ Number of main pumps	N/A	01	N/A
	➢ Jockey Pump out put	N/A	180 LPM	N/A
	➢ Jockey pump head	N/A	60 m	N/A
	➢ Standby Pump out put	N/A	2280 LPM	N/A
	➢ Standby Pump Head	N/A	60 m	N/A
	➢ Auto Starting/Manual Stopping	N/A	Provided	N/A
	➢ Pump House Access	N/A	Provided	N/A
	Terrace level	**(Provided & Maintained by Mall Management)**		
	➢ Discharge of pump	450 LPM	Provided	MR
	➢ Head of the pump	40 m	Provided	MR
	➢ Power Supply	Required	Provided	MR
	➢ Auto Starting of pump	Required	Provided	MR
14.	**Captive Water Storage for fire fighting**	**(Provided & Maintained by Mall Management)**		
	• Underground tank capacity	N/A	2,00,000 ltrs	N/A
	➢ Draw-off connection	N/A	Provided	N/A
	➢ Fire service inlet	N/A	Provided	N/A
	➢ Access to tank	N/A	Provided	N/A
	• Overhead Tank capacity	20,000 Ltrs.	30,000 Ltrs.	MR
15.	**Exit Signage.**	Required	Provided	MR
16.	**Provision of Lifts.**	**(Provided & Maintained by Mall Management)**		
	a) Pressurization of Lift Shaft	N/A	Provided	N/A
	b) Pressurization of Lift lobby	N/A	N/A	N/A
	c) Communication In lift Car	Required	Provided	MR
	d) Fireman's Grounding Switch	Required	Provided	MR
	e) Lift Signaga's	Required	Provided	MR

17.	**Standby power supply**	Required	Provided	MR
18.	**Refuge Area.**			
	a) Total Area	N/A	N/A	N/A
	b) Location	N/A	N/A	N/A
19.	**Fire Control Room**			
	a) Detector System Panel	N/A	N/A	N/A
	b) Flow Switch Panel	N/A	N/A	N/A
	c) PA System Panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building Floor Plans	N/A	N/A	N/A
20.	**Special Fire Protection System for Protection of special Risks, if any:**	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection. Shortcoming issued vide letter no. F6/DFS/MS/EH/WZ/2026/15 dated 05/01/2026 found rectified.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no. F6/DFS/MS/2023/WZ/EH/42 dated 01/02/2023 renewal under rule 35 of the Delhi Fire Service Rule 2010 **is recommended**.

23/07/2026

Signature of the Inspecting Officer
Name : - Paras Kumar
Designation : - ADO (Rohini)

DO/NWS
23/7/2026

DY CFO/WZ
24/07/2026

CFO (WZ)
24/07/26

Pr. Director
CFO to issue
28/7/26

Recieved on 4/8/26
CFO (WZ)
21/8/26
A.K. MALIK

Dy. CFO (WZ)
06/08/2026

Contd :-