c132

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/EH/2026/SZ/ 54 Dated: 19/01/2026

To,
Sh. Sanjeev Yadav,
M/s Haldiram Marketing Pvt. Ltd.,
C-9, Malviya Nagar, New Delhi- 110017.

Sub: Regarding renewal of Fire Safety Certificate in r/o M/s Haldiram Marketing Pvt. Ltd. located at C-9, Malviya Nagar, New Delhi- 110017.

Sir,

This has reference to online application received through MCD portal vide ID-2025122616129 on the subject cited above. In this connection, it is to inform you that the above said assembly building was re-inspected by officer concerned of this department on 02/01/2026 in presence of Mr. Sai Ram and observed that of the shortcomings issued by this department vide letter No.F6/DFS/MS/SD/2025/EH/428 dated 12/11/2025 are still not complied (copy enclosed).

In view of above, the application for renewal of Fire Safety Certificate is not considered at this stage & rejected. The occupancy of the building/ premises in absence of requisites fire safety measures shall be at the risk and liabilities of the owner/ occupier.

Yours Faithfully

Enclose: As above.

16/1/26
(A.K. Malik)
Dy. Chief Fire Officer

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/SD/2025/ EH/428 Dated: 12/11/2025

To,

The Manager,
M/S Haldiram Marketing Pvt. ltd,
C-9, Malviya Nagar, New Delhi-110017.

Sub: Issuance of FSC (Fire Safety Certificate) in r/o M/S Haldiram Marketing Pvt. ltd. located at C-9, Malviya Nagar, New Delhi-110017.

Sir,

This has reference to ID No. 2025101314151 dated 13.10.2025, on the subject cited above, it is to inform you that the site was inspected by the officer concerned of this department on 25/10/2025 in the presence of Sh. Sai Ram (Manager) and the following shortcomings were observed:-

1. Main staircase found reduced to 1.5 m against the requirement of 2 m.
2. Smoke management system found removed in basement.
3. Exit Signage found removed.
4. Underground water tank found empty.
5. Pump not in auto mode provision.

In view of above, the case is rejected and Fire Safety Certificate (FSC) cannot be renewed at this stage. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

7/11/25

(A. K. Malik)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-
The Commissioner MCD, Civic Centre, New Delhi.