GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI–110001

No. F.6/DFS/MS/EH/NDZ/2026/360 Dated: 23/04 /2026

To

The Commissioner,
Municipal Corporation of Delhi,
Dr. SPM Civic Centre, New Delhi - 110002.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o M/s Haldiram Marketing Pvt. Ltd. located at PD Area Ground Floor, Tis Hazari Metor Station, Delhi - 110054.

Sir,

This has reference to MCD portal online application Id No.2026032503551 dated 25.03.2026 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 14.04.2026 and observed that the shortcomings intimated vide letter of even No.F.6/DFS/MS/EH/NDZ/2026/479 dated 17.03.2026 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building /premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Encl: As above.

Yours faithfully,

23/4/26

(Dr. S. K. Tomar)
Chief Fire Officer
Delhi Fire Service

Copy to:-
The Licensee,
M/s Haldiram Marketing Pvt. Ltd. located at PD Area Ground Floor, Tis Hazari Metor Station, Delhi - 110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/FH/NDZ/2026/ 479 Dated: 17/03/2026

To

The Commissioner,
Municipal Corporation of Delhi,
Dr. SPM Civic Centre, New Delhi - 110002.

Sub : Regarding issuance of Fire Safety Certificate (FSC) in r/o M/s Haldiram Marketing Pvt. Ltd. located at PD Area Ground Floor, Tis Hazari Metro Station, Delhi - 110054.

Sir,

This is in reference to your online application ID No. 20260218O1748 dated 18.02.2026 on the subject cited above. In this connection, it is to inform you that regarding issuance of a Fire Safety Certificate (FSC) for the Haldiram Marketing Pvt. Ltd., occupying an area of 325.16 sqm at the PD Area, Tis Hazari Metro Station, it is informed that the site was visited by the officer concerned from this department. During the inspection, it was observed that the fire and life safety systems have not been extended into the PD area in accordance with the specific guidelines and mandatory conditions issued vide this office letter No. F. 6/DFS/MS/BP/2025/391 dated 15.02.2025. The inspection revealed that the required augmentation of the underground fire water tank to 2,00,000 liters and the installation of the specified fire pump house capacities including electric pumps of 2850 LPM for hydrant and sprinkler systems have not been carried out.

Furthermore, essential fire safety arrangements such as hose reel and smoke management systems have not been extended into the proposed commercial area as per NBC Part 4 and UBBL-2016 requirements. Consequently, as the system is not extended in the PD area as per the prescribed guidelines, your application for the issuance of a Fire Safety Certificate is hereby rejected.

Yours faithfully,

17/3/26

(Dr. S. K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-
The Manager, M/s Haldiram Marketing Pvt. Ltd. at PD Area Ground Floor, Tis Hazari Metro Station, Delhi - 110054.