C/46

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/EH/SZ/2026/ 196 Dated: 03/03/2026

To,

The Commissioner,
Municipal Corporation of Delhi
Civic Center, New Delhi – 110002.

Subject: - Regarding Grant of Fire Safety Certificate in r/o M/s Hotel Daya Continental located at A – 6, Road no. 1, Mahipalpur Extn., New Delhi – 110037.

Sir,

Please refer to your MCD Portal application No. 2025062910713 dated 12/02/2026 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on 21/02/2026 in the presence of Mr. Mukesh Kumar (Manager) and observed that the shortcoming is still not complied with as issued by this department vide letter no. F.6/DFS/MS/GH/2023/SZ/509 dated 29/09/2023 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is **rejected.** The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

3/3/26

(A.K. Malik)
Dy. Chief Fire Officer
Delhi Fire Service

आज़ादी का अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI- 110001

No. F.6/DFS/MS/GH/2023/SZ/509

To

Dated: 29/09/2023

The Addl. Commissioner of Police,
Lic/Branch, 1st Floor, P.S Defence Colony
New Delhi 110049.

Sub: Regarding renewal of FSC in r/o M/s Hotel Daya Continental at A-6, Road No 1, Mahipalpur, Extension, New Delhi 110037

Sir,

This is in reference with MHA Portal ID 2023081014353 dated 12-09-2023 on the subject cited above. In this connection, the premises have been inspected by officer concerned of this department on 25/09/2023 in the presence of Mr. Mohan Singh of the Guest House. During the inspection, it was observed that the Guest House is running Ground plus Three Upper Floors. The shortcomings observed are as below:

1. Fire check doors not provided in the building as per clause 7.31 of UBBL 2016.
2. Smoke management system not provided in the building as per clause 7.31 of UBBL-2016
3. First Aid hose provided but found nonfunctional.
4. Carbon Monoxide detector not provided as per clause 7.31 of UBBL 2016.
5. Internal hydrant provided but found nonfunctional.
6. Terrace level fire fighting pump provided but found not functional.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. M/s Hotel Daya Continental at A-6, Road No 1, Mahipalpur, Extension, New Delhi 110037