d/19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/2026/School/ 105 Dated: 05/02/2026

To

The Principal
Little Star School,
T-1/8, Budh Vihar, Ph-I, Delhi-110086.

Sub:- Regarding issuance of Fire Safety Certificate in r/o Little Star School located at T-1/8, Budh Vihar, Ph-I, Delhi-110086.

Sir,

This has reference to letter received through online e-mail dated 29/12/2025 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 17/01/2026 in the presence of Sh. D.R. Gautam (Chairman) and it was observed that the shortcomings issued to the restaurant vide letter no. F6/DFS/MS/WZ/2020/125 dated 20/02/2020 have not been rectified completely till date. (Copy enclosed).

In view of above, grant of Fire Safety Certificate cannot be considered at this stage & rejected. Applicant may be requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of school is at your own risk & responsibility. The Statutory Authority may take suitable necessary action as deemed fit.

Encl: as above

Yours faithfully

03/02/26

S.K. Dua
Dy. Chief Fire Officer
Delhi Fire Service

OK Cy

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2020/125

Dated: 20/02/2020

To,

The Principal,
Little Star Model School,
T-1/8, Budh Vihar Phase-I,
Delhi -86

Sub: Issuance of Fire Safety Certificate in r/o Little Star Model School, T-1/8, Budh Vihar Phase-I, Delhi-86

Sir,

This is in reference with your letter No. LSMS-20/2019 dated 19.11.2019 received in outdoor diary no. O.D No. 25546 dated 19.11.2019, on the subject cited above. The premise was inspected by the concern nominated authority of this department in presence of Smt. Parmila Gautam (Principal) on 16.01.2020 to verify the compliance of fire prevention and fire safety measures required under the rules. Following shortcoming has been observed during inspection.

1. The width of Staircase is 1.51 & 1.37 mtr against the required width of 1.50 mtr.
2. The width of door is 0.83 mtr against the required width of one mtr.
3. 3000 ltrs Over Head water captive tank provided against the required capacity of 10,000 ltrs.
4. The required exit signage are not provided.
5. MOEFA is not provided in all exits.

In this regard as stipulated in sub Rule (1) of Rule 37 of DFS Act-2007 & Rules 2010 you are advised to apply again in Form "I" along with a certificate from Architect/ owner that all the fire prevention and fire safety measures are provided as per Rule 33 of DFS Act-2007/ Rules 2010 in the building/premise & duly filled Performa enclose herewith. The Form "I" is available on website of this department under.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/
http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours Faithfully,

(Dhrampal Bhardwaj)
Dy.Chief Fire Officer
Tel:-01125156707