GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI-110001

e-58

No.F6/DFS/MS/ SZ/2026/ 236 Dated: 15/06/2026

To,

The Executive Engineer,
CPWD, IIT Campus,
New Delhi- 110016.

Sub: Inspection report in r/o M/s. New Academic Building for NIEPA at 17-B, Sri Aurobindo Marg, New Delhi-110016.

Sir,

This has in reference to your application no-23(12)/Assistant Engineer (electrical)-1/IIT Project Electrical Division/2026/79 dated 04/05/2026, on the subject cited above. In this connection, it is to inform you that the premises was re-inspected by officer concerned of this department on 03/06/2026 in the presence of Mr. Satyapal, AE(E) to check the shortcomings already issued by this department vide letter No.F6/DFS/MS/SZ/2026/78 dated-17/03/2026 (Copy enclosed).

The following shortcomings are still not complied.

1. Pressurization in lift lobby at basement level is not provided.
2. Terrace pump of capacity 900 LPM is not provided.

In view of above Shortcomings, the application for issuance of fire safety certificate is rejected. The occupancy of the building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/Occupier. The licensing issuing Authority/Statutory Authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully,

(A.K. Malik)
Chief Fire Officer

Copy to: -

1. The Owner/Occupier of M/s. New Academic Building for NIEPA at 17-B, Sri Aurobindo Marg, New Delhi-110016.