GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

NO.F.6/DFS/MS/Outer-North/2026/346 Dated: 07/08/2026

To,

Sh. Shishir Jha, DGM (Operation)
Pragati Power Corporation Ltd.,
PPS -III, Sector – 5, DSIIDC Industrial Area,
Bawana, Delhi - 110039.

Sub: - Regarding issuance of FSC/NOC in r/o **Pragati Power Corporation Ltd., PPS -III, Sector – 5, DSIIDC Industrial Area, Bawana, Delhi - 110039.**

Sir,

This has a reference to letter no. ED/(PPS-III/Bawana/F-9/2026-27/43 dated 09/04/2026 on the subject cited above. In this connection, it is to inform you that the premise was visited by the officer concerned of this department on dated 25/07/2026 in the presence of Sh. Shishir Jha, DGM (Operation). During course of inspection, the shortcomings observed are as below: -

1. Width of staircase at Upper floors in Admin Bldg. is not provided as per requirement.
2. Width of staircase in basements (Store Building) is not provided as per requirement.
3. Smoke Management System in basements (Store Building) is not provided as per requirement.
4. First-Aid Hose Reel is not provided as per requirement.
5. MOEFA is not provided as per requirement.
6. Public Address System found nonfunctional.
7. Yard Hydrants Hose box found missing at some places.
8. Draw-off connection and fire service inlet found removed.
9. Flow switch panel & Building floor plan are not provided.

In view of the above, application for fire safety certificate is rejected. You are requested to rectify the above shortcomings under intimation to this department for further action in the matter. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of owner/occupier of the establishment.

Yours faithfully,

7/8/26

(Dr. S. K. Tomar)
Chief Fire Officer
Delhi Fire Service