GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आजादी का अमृत महोत्सव

No. F6/DFS/MS/WZ/2026/790 Dated: - 14/08/2026

To,

Sh. Ankit Anand (Principal),
Punjab and Sind Bank, Staff Training College,
Institutional Area, Sector-3, Rohini, Delhi.

Subj.:- Regarding issuance of Fire Safety Certificate in respect of Punjab Sind Bank, Staff Training College, located at Institutional Area, Sector-3, Rohini, Delhi.

Sir,

This has reference to the Form 'I' dated 26/05/2026 on the subject cited above. In this connection, it is to inform you that the said building was re-inspected by the officer concerned of this department on 24/07/2026 in the presence of Sh. S. K. Sharma to check compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/2020/2148 dated 27/08/2020.

During the course of inspection, it has been observed that the college management has rectified some of the shortcomings, the status is under as: -

S. no.	Shortcomings	Status
1.	Ventilation System provided but not functional	Not yet rectified
2.	Door closer device for fire check door found removed	Not yet rectified
3.	Pressurization System of lift lobby at basement not provided	Not yet rectified
4.	Dead end is observed at 4th floor	Rectified
5.	Directions of fire doors in basement and terrace are in opposite direction of flow of exit	Not yet rectified
6.	Electrical shafts are not sealed at every floor	Rectified
7.	Staircases are not segregated at Ground floor to basement	Rectified

In view of the above, the application for issuance of Fire safety Certificate cannot be considered at this stage & **rejected**. You are advised to rectify the above mentioned shortcomings under intimation to this department & till such time occupancy of the building/premises in absence of requisite fire safety arrangements shall be at your own risk and responsibility.

Yours faithfully,

(A.K. Malik)
Chief Fire Officer
Delhi Fire Service