GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/School/2025/SZ/ 839

Dated: 27 / 11/2025

To,

The Principal,
SES, BABA NEBHRAJ Sr. Sec. School
Lajpat Nagar – I, New Delhi – 110024.

Subject: - Regarding issuance of Fire Safety Certificate in r/o SES, BABA NEBHRAJ Sr. Sec. School located at Lajpat Nagar – I, New Delhi – 110024.

Sir,

Please refer to your outdoor dairy No. 7728 dated 31/10/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 12/11/2025 in the presence of Mrs. Meenakashi Lalwani (H.O.S) & Mr. Naveen Kumar Yajurvedi (ASO) and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/SZ/2025/312 dated 02/05/2025 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

24/11/25

(A.K.Malik)
Dy. Chief Fire Officer
Delhi Fire Service

Enclose as above

Copy to: -

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block - C, Defence Colony, New Delhi - 110024.

c/37

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आज़ादी का अमृत महोत्सव

No. F6/DFS/MS/School/SZ/2025/ 312 Dated: 02/05/2025

To

The Principal,
SES, Baba Nebhraj Sr. Sec. School,
Lajpat Nagar-1, New Delhi-110024.

Sub:- Regarding issuance of Fire Safety Certificate in respect of **SES, Baba Nebhraj Sr. Sec. School, Lajpat Nagar-1, New Delhi-110024.**

Sir,

With reference to letter bearing outdoor diary no. 254 dated 04.04.2025 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 24.04.2025 in the presence of Mr. Naveen Kumar Yajurvedi (ASO) and following shortcomings were observed:-

1. Hose reel found removed.
2. Fire pump found not in auto mode.
3. Terrace Fire Tank capacity of 10,000 liters has not been provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)
Director
Delhi Fire Service

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.