GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/WZ/EH/2025/ 393 Dated: 06/10/2025

To,

Mr. Sandeep Joshi,
House No.A-24 Shyam Vihar,
Phase-2 Najafgarg, Dindapur,
New Delhi-110043.

Sub: Renewal of FSC in r/o M/s Tata Starbucks Pvt. Ltd. located at upper ground floor, Plot No.25, North West Avenue Club Raod, Punjabi Bagh, New Delhi-110026.

Sir,

This is in refer to your online application No. 2025091213401 dated 12.09.2025 received in this department on the subject cited above. In this connection it is to inform you that the building was visited by officer of this department in presence of Mrs. Deepika (Store Manager) on dated 22.09.2025 & it has been observed that the shortcoming already issued by this department letter of even No. 335 dated 11.08.2025 is not yet rectified (Copy enclosed). Therefore applicant is advised apply through the said online portal for further consideration in the matter after rectifying all the shortcomings.

Yours Faithfully

Encl; as above

M. K Chattopadhyay
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-
1. MCD Portal ID-2025091213401 dated 12.09.2025.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/WZ/EH/2025/335 Dated: 11/08/2025

To,

Mr. Sandeep Joshi,
House No.A-24 Shyam Vihar,
Phase-2 Najafgarg, Dindapur,
New Delhi-110043.

Sub: Renewal of FSC in r/o M/s Tata Starbucks Pvt. Ltd. located at upper ground floor, Plot No.25, North West Avenue Club Raod, Punjabi Bagh, New Delhi-110026.

Sir,

This is refer to online application no. 2025071311312 dated 13.07.2025, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on **26.07.2025**, in presence of **Mrs. Deepika (Store Manager)** to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for **renewal of FSC is rejected** under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Smoke management system is not provided.
2. Hoses & branch found missing from hose box.
3. Pump house/pumps are now common with Juri Restaurant instead of standalone fire protection system for restaurant in last renewal. Therefore, clarification is required on control of fire protection system.
4. 5000 ltrs Over Head water captive tank provided against the required capacity of 10,000 ltrs.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" /MCD Portal with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:
http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

Yours faithfully

8/8/2025

(Virendra Singh)
Chief Fire Officer

Copy To:-

1. MCD Portal Id- 2025071311312 dated 13.07.2025.