235

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/SZ/2026/712 Dated: 22/07/2026

To,

The Commissioner MCD,
Dr. S.P.M. Civic Centre, Minto Road,
New Delhi- 110002.

Sub: Regarding renewal of FSC from fire safety point of view in r/o M/s. The Orion Elite (A Unit of Strengthening India Pvt Ltd.) located at H-3, Green Park Extension, New Delhi-110016.

Sir,

Please refer to your online application No. 2026060808399 dated-15/06/2026, on the subject cited above. In this connection, it is to inform you that the building/premises was inspected by the officer concerned of this department on 03/07/2026 in the presence of Sh. Abhimanyu (owner) and observed that the shortcomings already communicated by this department vide letter No F6/DFS/MS/GH/NDZ/143 dated 01/04/2025, is still not complied so far.

In view of above, the application for issuance of Fire Safety Certificate is not considered at this stage.

Yours Faithfully,

22/7/26

(A.K. Malik)
Chief Fire Officer

Copy to-

1. Owner/Occupied-, M/s. The Orion Elite (A Unit of Strengthening India Pvt Ltd.) located at H-3, Green Park Extension, New Delhi-110016. (Online application No. 2026060808399 dated-15/06/2026).

c/28

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/GH/NDZ/ 143 Dated:- 01/04/2025

To,

The Manager,
M/s The Orion Elite (A Unit of Strengthening India Pvt. Ltd),
H-3, Green Park Extension, New Delhi-110016.

Sub: Issuance of FSC (Fire Safety Certificate) in **r/o M/S The Orion Elite (A Unit of Strengthening India Pvt. Ltd), H-3, Green Park Extension, New Delhi-110016.**

Sir,

This has reference to on line ID No. 2025031103276 dated 11.03.2025, on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 22/03/2025 in the presence of Manager and following shortcomings were observed: -

1. Smoke management system is not provided in basement.
2. 02 staircase of 1.5 meter is not provided in the basement.
3. Width of corridor of 1.80 m is not provided.

Hence, the case is rejected and Fire Safety Certificate (FSC) cannot be issued at this stage due to above shortcomings. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

(Atul Garg)
DIRECTOR
01123414000