GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/EH/2025/NDZ/ 488 Dated: 23 /12/2025

To,

The Commissioner,
Municipal Corporation of Delhi,
Civic Centre, Minto Road,
New Delhi - 110002.

Subject: - Regarding renewal of Fire Safety Certificate in r/o Zaika Bazar located at 6, Parmesh Complex – II, Karkardooma Community Center, Delhi – 110092.

Sir,

This has refer to your MCD application ID No. 2025120315389 dated 03.12.2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 10/12/2025 in presence of Mr. Chakar Goshi (Manager) and observed that the shortcomings issued by this department vide letter no. F6/DFS/MS/NDZ/2025/EH/459 dated 02/12/2025 (copy enclosed) have still not complied so far.

In view of above, the application for issuance of Fire Safety Certificate is rejected. Further, the occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Encl: as above

22/12/25

(Dr. S.K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to: -

1. Authorized Signatory, Zaika Bazar 6, Parmesh Complex – II, Karkardooma Community Center, Delhi – 110092

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/NDZ/GH/2025/ 454 | 459

Dated: 02 / 12 / 2025

To

The Commissioner,
Municipal Corporation of Delhi,
Civic Centre, Minto Road,
New Delhi

Sub: Regarding renewal of Fire Safety Certificate in respect of Zaika Bazar, 6, Parmesh Complex II, Karkardooma Community Centre, Delhi - 92.

Sir,

Please refer to online application No. 2025111514888 dated 15/11/2025 on the subject cited above. In this connection, it is to inform you that the said building was inspected by the officer concerned of this department on 19/11/2025 in the presence of Sh. Raj Nath Bhatt, Manager and following shortcomings were observed: -

1. Overhead water storage tank of 5,000 Ltrs was found removed.
2. Terrace pump provided but found non-functional.
3. Fire extinguishers provided but refilling is not done.
4. Hose reel was provided in kitchen at second floor and ground floor but found non-functional. Whereas, hose reel found removed at first floor.
5. Manually Operated Electrical Fire Alarm provided but found non-functional.
6. Exit signages found removed.

Keeping in view of the above shortcomings, the application for renewal of Fire Safety Certificate cannot be considered at this stage and stand rejected. Further, the occupancy of the building premises in the absence of requisite fire safety measures shall be at the risk and liability of the owner/occupier.

Yours Faithfully,

01/12/2025

(D. B. Mukherjee)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to: Smt. Poonam Dhingra (Properitor), Zaika Bazar, 6, Parmesh Complex II, Karkardooma Community Centre, Delhi - 92.