GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52025122300884 **Dated: 26-02-2026**

SHORTCOMING(S)

With reference to your application ID **52025122300884** dated **26-02-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Saraswati Public Secondary School** at **Budh Vihar Madoli,Delhi 110093** from fire safety point of view in presence of **Mrs Santos Aggarwal** on dated **06/02/2026** During the course of inspection following observations were made:-

1. First Aid-Hose reels provided but not functional.
2. Down-comer are not provided.
3. Terrace pump capacity 450 lpm and 40 meters head is not provided.
4. An over head tank capacity 5,000 liters is not provided.
5. Exit Signage not provided.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Dr.S.K.Tomar
Dy.Chief Fire Officer

Copy to:-
1. Akash Aggarwal , C-223 , STREET NO-6, HARDEV PURI SHAHDARA, DELHI, 110093
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.