GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026041502252 **Dated: 16-05-2026**

SHORTCOMING(S)

With reference to your application ID **52026041502252** dated **16-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Uttranchal Public School** at **Kamal Pur, Burari, Delhi-110084** from fire safety point of view in presence of **Sh. Sanjay, Principal** on dated **06/05/2026** During the course of inspection following observations were made:-

1. First-Aid Hose Reel found removed at 2nd floor and 3rd floor.
2. The overhead water storage tank of 4,000 liters capacity is inadequate against the required capacity of 5,000 liters

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

S.K.DUA
Chief Fire Officer

Copy to:-
1. SANJAY SINGH , HOUSE NO C-4/176A, LAWRENCE ROAD, ONKAR NAGAR, DELHI, 110035
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.