GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026051502931 **Dated: 29-05-2026**

SHORTCOMING(S)

With reference to your application ID **52026051502931** dated **29-05-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **Khalsa Girls Sr. Sec. School** at **Chuna Mandi, Paharganj, New Delhi** from fire safety point of view in presence of **Sh. Dhuli Lal Meena, Office Assistant** on dated **22/05/2026** During the course of inspection following observations were made:-

1. Smoke Management System found removed in Basement.
2. Terrace Pump provided 180 LPM of capacity against the required capacity of 450 LPM.
3. Automatic operation of Terrace pump found removed.
4. Overhead water storage tank provided 9,900 Ltrs of capacity against the required capacity of 15,000 Ltrs.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

Dr.S.K.Tomar
Chief Fire Officer

Copy to:-
1. Khalsa Girls Sr Sec School , 1886-87, Chuna Mandi , Pahar Ganj, New Delhi, 110055
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.