GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

Application ID. 52026102706032 **Dated: 23-11-2026**

SHORTCOMING(S)

With reference to your application ID **52026102706032** dated **23-11-2026** on the subject cited above, it is informed that officer concerned of this department inspected the **CM Shri School** at **Rajiv Ratan Awas, Baprola, New Delhi - 110043.** from fire safety point of view in presence of **Dr. Sudhir Kumar - Principal** on dated **03/11/2026** During the course of inspection following observations were made:-

1.First Aid Hose Reel provided but found nonfunctional.
2.Automatic Sprinkler System provided but found nonfunctional.
3.Internal and Yard Hydrants provided but found nonfunctional.
4.Terrace Level Pump is of 900 LPM provided but found nonfunctional.

In view of the above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore, the application is rejected with the directions to apply again after compliance of above mentioned shortcomings under intimation to this office for further course of action.

A.K.Malik
Chief Fire Officer

Copy to:-
1. CM SHRI SCHOOL RRA BAPROLA , CM SHRI SCHOOL , RAJIV RATAN AWAS, NEAR ROYAL PALACE BAPROLA, WEST DELHI, 110043
2. The Concerned Local/Statutory Authority –

This letter is computer generated and does not require signature.