c183

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6 /DFS/MS/Coaching/2025/ 141 Dated: 24 /11/2025

To

The Executive Engineer
Municipal Corporation Delhi
Civic Centre, New Delhi.

Sub: Regarding FSC in r/o - A-1/171- A, Janakpuri, Delhi-110058.

Sir,

This has reference to MCD Online ID-70000209 dated Nil, on the subject cited above. In this regard, it is to inform that the site was inspected by the officer concerned of this department on 15/11/2025 in the presence of Mr. Prakash Jha and the following shortcomings are observed:

1. One staircase is provided in basement against the requirement of two staircase of width 1.5m.
2. The width of the 01 staircase is 1.2 m against the requirement of 1.5m.
3. Sealing of shaft and fire check door are not provided.
4. Sprinkler system is not provided in the basement.
5. Pump is not on auto- starting mode.
6. Staircase serving from basement is not segregated at ground floor.

In view of above, Fire Safety Certificate (FSC) cannot be considered at this stage and the case is rejected. Therefore, you are requested to rectify the above shortcomings and re-submit for further consideration in the matter.

Yours faithfully,

22/11/25

(A. K Malik)
Dy. Chief Fire Officer