आज़ादी का अमृत महोत्सव

FORM 'H' : FORM FOR ISSUING FIRE SAFETY CERTIFICATE
[See sub-rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/NZ/2026/244 Dated: 27/11/2026

FIRE SAFETY CERTIFICATE

Certified that the M/s Bling Hall (Old Name Ornate) located at M/s Yadu Green Motel, Kh. No. 42/25, 52/9, 52/10,52/11, 53/5, 53/6 Min, Main GT Karnal Road, Village-Bakoli, Delhi-110036 owned / occupied by M/s Yadu Green Motel, comprised of Ground Floor only (Semi Pucca Steel Structure) was earlier issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/2023/Motel/WZ/201 dated 01/05/2023. The premises was re-inspected by the officer concerned of this department on 14/11/2026 in the presence of Sh. K.N. Chaudhary (Manager) and observed that all the Fire prevention and Fire Safety arrangements provided in the premises found in good working condition. The premises have therefore, deemed complied with rule 33 of the Delhi Fire Service rules, 2010 and that the building / premises is fit for occupancy Class "Assembly" (Banquet Hall) with effect from 27/11/2026 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on ...27.11.2026..... at New Delhi.

(M.K. Chattopadhyay)
Dy. Chief Fire Officer
Delhi Fire Service.

Copy to :-

1. Sh. K.N. Chaudhary (Manager), M/s Bling Hall (Old Name Ornate) located at M/s Yadu Green Motel, Kh. No. 42/25, 52/9, 52/10,52/11, 53/5, 53/6 Min, Main GT Karnal Road, Village-Bakoli, Delhi-110036.
2. MCD portal ID-2026110511434 dated 05/11/2026.

Conditions for the validity of Fire Safety Certificate:-

1. All the fire safety arrangement provided there in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non- functional fire safety measure shall be at the responsibility of the management.
3. The trained fire- fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. Basement shall be used strictly as per Building By-Law.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in.

INSPECTION REPORT N/15

1. Name & address of the building : M/s Bling Hall (Old Name Ornate), located at M/s Yadu Green Motel, Kh. No. 42/25, 52/9, 52/10,52/11, 53/5, 53/6 Min, Main GT Karnal Road, Village-Bakoli, Delhi-110036.
2. Building is comprised of : Semi Pucca Steel Structure (Ground Floor only)
3. Type of Occupancy : Assembly
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/2023/Motel/WZ/201 dated 01/05/2023
6. Fire Safety directives Letter No. : F6/DFS/MS/BP/2022/73 dated 12/01/2023
7. Date of inspection : 14/11/2026
8. Name of the Inspecting Officer : A.D.O. (S.B.)
9. Name and designation of Officer from the building side : Sh. K.N. Chaudhary (Manager)
10. Year of Construction : 2022
11. Application No. & dated : 2026110511434 Dated 05/11/2026

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC & BBL Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	09 mtr	Provided	MR
	• Gate width	05 mtr	Provided	MR
	• Width of internal road	NA	NA	NA
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases	**Ground Floor Only**		
	• Upper floors	NA	NA	NA (Ground Floor Only)
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper floors	NA	NA	NA (Ground Floor Only)
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	d. No of continuous staircase to terrace	NA	NA	NA
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	2.00 mtr	Provided	MR
3.	Compartmentation			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4.	Smoke managements System			
	• Basements	NA	NA	NA
	• Ground Floor Banquet Hall	12 a/c per hour	Provided	MR
5.	Fire Extinguishers			
	• Total numbers	1@300SQM	Provided	MR
	• Types	ISI marked ABC/CO_2	Provided	MR
	• IS marking	Required	Provided	MR

6.	First – Aid Hose Reels			
	• Total numbers on each floor	1	1	MR
	• Length of hose reel hose	30 mtr.	30 mtr.	MR
	• Nozzle diameter	5mm.	5mm.	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Heat & Smoke	Provided	MR
	• Location of Main Panel	Ground Floor	Provided	MR
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	• Basements	NA	NA	NA
	• Ground Floor Banquet Hall	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants			
	• Size of riser/down-comer	150 mm	Provided	MR
	• Number of hydrants per floor	1	Provided	MR
	• Hose Box	1	Provided	MR
12.	Yard Hydrants			
	• Total number of hydrants	Required	Provided	MR
	• Hose Box	Required	Provided	MR
13.	Pumping Arrangements			
	• Ground Level			
	• Discharge of main pump	2850 LPM	Provided	MR
	➢ Head of main pump	40 M	Provided	MR
	➢ Number of main pumps	1	Provided	MR
	➢ Jockey pump out put	180 LPM	Provided	MR
	➢ Jockey pump head	40 M	Provided	MR
	➢ Standby Pump out put	2850 LPM	Provided	MR
	➢ Standby Pump Head	40 M	Provided	MR
	➢ Auto Staring/Manual stopping	NA	NA	NA
	➢ Pump House Access	Required	Provided	MR
	• Terrace level			
	➢ Discharge of pump	900 LPM	Provided	MR
	➢ Head of the pump	40 M	Provided	MR
	➢ Power supply	Required	Provided	MR
	➢ Auto starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	1,00,000 ltr	1,00,000 ltr	MR
	➢ Draw of connection	Required	Provided	MR
	➢ Fire service inlet	Required	Provided	MR
	➢ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	10,000 lts.	Provided	MR

N-17

15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➢ Pressurization of Lift Shaft	NA	NA	NA
	➢ Pressurization of lift lobby	NA	NA	NA
	➢ Communication in lift Car	NA	NA	NA
	➢ Fireman's Grounding Switch	NA	NA	NA
	➢ Lift Signage	NA	NA	NA
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area			
	➢ Total area	N/A	N/A	N/A
	➢ Location	N/A	N/A	N/A
19.	Fire control room			
	➢ Detector system panel	Required	Provided	MR
	➢ Flow Switch Panel	NA	NA	NA
	➢ PA System Panel	Required	Provided	MR
	➢ Battery backup	Required	Provided	MR
	➢ Building Floor Plans	NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA

Note:-Shortcoming issued by this department vide Letter No.F6/DFS/MS/WZ/Motel/ 2026/101 Dated 09.04.2026 have been complied.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal wiring has also been provided.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F6/DFS/MS/2023/Motel/WZ/201 dated 01/05/2023 renewal under rule 35 of the Delhi Fire Service rules 2010 is **recommended**.

ADO(SB)
17/11/26

Signature of the Inspecting Officer
Name : Rajiv Kumar Sinha
Designation : A.D.O. (S.B.)

DO(North) AK Jaiswal 17/11/2026

By CFO(H.Q.)

17/11/2026

Principal Director By CFO to issue.

18/11

By CFO

18/11

DO(North)

20/11/2026

P.T.O.

N-18

ADO/S.B.

Sir, draft letter is put up for sign please

ADO(SB)
25/11/26

Dy CFO(HQ)

25/11

MS Cell
24.11.26
Uploaded
24/11/26