GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

Dated: 13.02.2026

No: F.6/DFS/MS/2026/WZ/41

To,

The Executive Engineer (E),
Electrical Division-3/ DDA,
Siri Fort, Behind Gargi College,
New Delhi-110049.

Sub:- Regarding issuance of Fire Safety Certificate in respect of M/s DDA Sports Complex located at A4/A6, Paschim Vihar, New Delhi - 110063

Sir,

This has reference to your e mail id dated 18/12/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said Sports complex building has been carried out by officer concerned of this department on ..2026 to see the compliance of the requisite fire safety measures. Mr. was present at the time of inspection.

During the course of inspection it was observed that building is comprised of Ground floor having Gym, Swimming Pool, Various sport court and Office block. Your request for issuance of FSC is rejected as the following shortcomings were observed:-

1. Door width of Gym found 2 m and 1 m against the required width of 2 m for each door.
2. Fire extinguishers not provided.
3. First aid hose reels not provided.
4. MOEFA not provided.
5. Internal hydrant not provided.
6. Terrace level pump of 900 lpm discharge capacity found not provided.
7. Overhead tank of 20000 ltrs capacity found not provided.
8. Exit signage's found not provided.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for issuance of Fire Safety Certificate. Till such time the occupancy of the building is at the risk and responsibility of owner/ occupier.

Yours Faithfully

12/02/26

(S.K. Dua)
Dy. Chief Fire Officer (WZ)
Delhi Fire Service

Copy to :-

1. The Manager, DDA Sports Complex, A 4/ A 6, Paschim Vihar, New Delhi-63.