GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/SZ/2026/293 Dated: 15/07/2026

To,

The Commissioner MCD,
Dr. S.P.M. Civic Centre, Minto Road,
New Delhi- 110002.

Sub: Regarding renewal of FSC from fire safety point of view in r/o M/s. Plot no E-14, Hauz Khas Enclave, New Delhi.

Sir,

Please refer to your online application No. 10122251 dated-29/06/2026, on the subject cited above. In this connection, it is to inform you that the building/premises was inspected by the officers concerned of this department on 09/07/2026 in the presence of Sh. Parveen kumar (J.E) & Manoj Kumar (A.E) MCD and observed that the shortcomings already communicated by this department vide letter No F6/DFS/MS/SZ/2026/248 dated 18/06/2026, is still not complied so far.

In view of above, the application for issuance of Fire Safety Certificate is not considered at this stage.

Yours Faithfully,

15/7/26

(A.K. Malik)
Chief Fire Officer

Copy to-

1. Owner/Occupied-, M/s. Plot no E-14, Hauz Khas Enclave, New Delhi-110016. (Online application No. 10122251 dated-29/06/2026).

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI

No. F6/DFS/MS/SZ/2026/ 248 Dated: 18/06/2026

To,

The Commissioner MCD,
Civic Centre, Minto Road,
New Delhi- 110002.

Sub: Regarding issuance of FSC from fire safety point of view in respect of Plot No. E-14, Hauz Khas Enclave, New Delhi.

Sir,

Please refer to online applications vide ID No. 10118754 dated- 04/06/2026. In this connection, it is to inform you that the building/premises was inspected by the officers concerned of this department DO(SD), ADO(BCP) on 09/06/2026 with Sh. Parveen Kumar JE(Bldg.) MCD & Sh. Manoj Kumar AE(Bldg.) MCD. During the inspection the following shortcomings were observed.

1. Fire check doors are not provided in the basement at staircase for compartmentation.
2. Smoke management is not provided in the basement.
3. Lift lobby is not provided in the basement.
4. Fireman switch is not provided in the lift.
5. Exit signage's are not provided.

In view of above, the Fire Safety Certificate cannot be issued at this stage & case is rejected.

Yours faithfully,

18/6/26

A. K. Malik
Chief Fire Officer

Copy To: -

1. The Owner/occupier, M/s Plot No. E-14, Hauz Khas Enclave, New Delhi. (Online online applications vide ID No. 10118754 dated-04/06/2026)