C102

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No.F6/DFS/MS/EH/2026/NDZ/664 Dated: 03/08/2026

FIRE SAFETY CERTIFICATE

Certified that the **M/s Kamals A Unit of Kammal Sweet LLP (earlier name Chirag Foods)** is running at ground floor of the building comprised of basement (storage), ground plus two upper floors at located at C-31-32, No.11, Madhu Vihar, Delhi-110092, owned/occupied by Kamals A Unit of Kammal Sweet LLP, was issued FSC vide letter No. F.6/DFS/MS/EH/NDZ/2023/60 dated 15/02/2023. The premises was re-inspected by the officer concerned of this department on dated 27/06/2026 in the presence of Sh. Kamal Kumar Gupta, Owner and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy Group 'D' "Assembly Building' (**Eating House at Ground floor)** with effect from .03/08/2026for a period of **three** years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on.....03/08/2026.....at New Delhi by

11/8/26

(Dr. S. K. TOMAR)
CHIEF FIRE OFFICER
DELHI FIRE OFFCIER

O/C E

To:-

1. The Commissioner, MCD, Civic Centre, New Delhi: to ensure the occupancy a detailed above.
2. Sh. Kamal Kumar Gupta, Sh. Kamal Kumar Gupta, **M/s Kamals A Unit of Kammal Sweet LLP** C-31-32, No.11,Madhu Vihar, Delhi-110092.
   MCD ID NO **2026060908517**

Conditions for the validity of Fire Safety Certificate:-

1. FSC is valid for ground floor only.
2. All the means of escape shall be kept free of all type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
6. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on **www.dfs.delhigovt.nic.in**

N/12.

INSPECTION REPORT

1. Name & address of the building : **M/s Kamals A Unit of Kammal Sweet LLP**
   C-31-32, No.11, Madhu Vihar, Delhi-110092
2. Building is comprised of : B+G+2 upper floor but restaurant is running at Ground Floor only
   Type of Occupancy : Assembly (Restaurant)
3. Type of Case : Renewal
4. Details of Previous NOC letter : F6/DFS/MS/EH/NDZ/2023/60 Dated:15/02/2023
5. Fire Safety directive letter No : NBC Part IV
6. Date of Inspection : 30/06/2026
7. Name of the Inspecting officers : Deepak Kumar, ADO (Shd.)
8. Name and designation of Officer from the building side : Sh. Kamal Kumar Gupta, Owner
9. Year of Construction : 2001
10. Applicant's letter No 2026060908517 dated 09/06/2026

Sr. No.	Minimum Standards on fire prevention and fire safety U/R33	NBC Part IV Requirements	Provided at Site	Remarks MR/NMR
01	Access to building			
	• Road width	06 m	10 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
02	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	• Upper Floor	N/A	01 nos. to access terrace pump	N/A
	• Basement	N/A	02 nos.	N/A
	b. Width of Staircases			
	• Upper Floor	N/A	N/A	N/A
	• Basement	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	N/A	01 no.	N/A
	e. width of Corridor	N/A	N/A	N/A
	f. No. of doors	02 nos.	02 nos.	MR
	g. Door Size	1.50 mtr	1.50 mtr each	MR
03	Compartmentation.			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire rating of shaft door	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
04	Smoke Management System			
	• Basement	N/A	N/A	N/A
	• Upper floor	Required	Provided (exhaust)	MR
05.	Fire Extinguishers.			
	• Total numbers	06 nos.	06 nos.	MR
	• types	ABC/CO_2	ABC/CO_2	MR
	• ISI marking	Required	Provided	MR

2

N/13.

06	First-aid-Hose Reels.			
	Total numbers on each floor	01	01	MR
	• Length of hose reel hose	30 mtr.	30 mtr.	MR
	• Nozzle diameter	05 mm	05 mm	MR
07	Automatic fire detection and alarming system.			
	• Type of detectors	N/A	N/A	N/A
	• Location of main panel	N/A	N/A	N/A
	• Location of repeater panel	N/A	N/A	N/A
	• Alternate source of power	N/A	N/A	N/A
	• Hooter's location	N/A	N/A	N/A
08	MOEFA	Required	Provided	MR
09	Public address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	• Basement	N/A	N/A	N/A
	• upper floor	N/A	N/A	N/A
	• sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	100 mm	100 mm	MR
	• Number of hydrants per floor	01 no.	01 no.	MR
	• Hose Box	01 no.	01 no.	MR
12	Yard Hydrants.			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
13	Pumping Arrangements			
	• Ground Level			
	➢ Discharge of main Pump	N/A	N/A	N/A
	➢ Head of Main Pump	N/A	N/A	N/A
	➢ Number of main pumps	N/A	N/A	N/A
	➢ Jockey pump out put	N/A	N/A	N/A
	➢ Jockey pump head	N/A	N/A	N/A
	➢ Standby pump out put	N/A	N/A	N/A
	➢ Standby pump Head	N/A	N/A	N/A
	➢ Auto Starting /Manual stopping	N/A	N/A	N/A
	➢ Pump House Access	N/A	N/A	N/A
	• Terrace Level			
	➢ Discharge of pump	900 lpm	900 lpm	MR
	➢ Head of the Pump	40 m	40 m	MR
	➢ Power supply	Required	Provided	MR
	➢ Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.			
	• Underground tank capacity	N/A	N/A	N/A
	➢ Draw-off connection	N/A	N/A	N/A
	➢ Fire service inlet	N/A	N/A	N/A
	➢ Access to tank	N/A	N/A	N/A
	• Overhead Tank capacity	20,000 ltrs	20,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication in lift car	N/A	N/A	N/A
	• Firemen's grounding switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A

N/14.

17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection system provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rule. The FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2023/60 Dated:15/02/2023 **renewal under rule 35 of the Delhi Fire Service Rules, 2010 is recommended.**

Last date:- 08/07/2026

01/07/2026.

Signature of the Inspecting Officer
Name :-Deepak Kumar
Designation :-ADO (Shahdara)

DO (ED)

02/07/26

CFO (East Zone)

Pl. speak.

2/7/26

DO (ED)

03/07/26

Spoken on 03/07/26.

In previous inspection report the width of door was 2.0 m now you have mentioned 1.5 m. please clarify.

04/07/26

ADO (Shad)

Sir, The actual width of Door is 1.5 mtr which is adequate as per laws as the sitting capacity is less than 150. Submitted pl.

04/07/2026

D.O (ED).

04/07/26

P.T.O.